Application/Control Number: 09/749,370

Art Unit: 2833

None of prior art teaches or suggest the apparatus further comprising the first guide pin is threaded on the first bolt; and the second guide pin is threaded on the second bolt; wherein the first guide pin and the second guide pin secure the mounting plate to the first bolt and the second

Page 8

bolt, and combination of all the claim above.

12. Wu et al (US6007360) is cited to show the guide socket having end member 4 including a thread engaging to thread inside the screw 41.

Conclusion

13. Any inquiry concerning this communication or earlier communications from the examiner should be directed to Phuongchi T Nguyen whose telephone number is (703) 305-0729. The examiner can normally be reached on Monday through Thursday from 8:00AM to

4:30PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Paula Bradley can be reached on (703) 308-2319. The fax phone numbers for the organization where this application or proceeding is assigned are (703) 305-7723 for regular communications and (703) 305-7723 for After Final communications.

Any inquiry of a general nature or relating to the status of this application or proceeding should be directed to the receptionist whose telephone number is (703) 308-7722.

May 6, 2001

Gary Paumen
Primary Examiner